



Flint Hills Resources, LP Work Order Details

Org: FHR-PE
Site: PE

WO #: PE28087

WO Desc: R-15 auto M1 vale dripping when pumping

Parent WO#:

WO Long Desc: styrene

WO Priority: 2

Location: E-R-15

REACTOR 15

Asset: 1347819

REACTOR 15

Asset Service:

Entry Date: 2/9/2011

WO Status: CLOSE

Action Code: LDAR

Project #:

Originator: James Jennings

Status Date: 8/9/2011

Work Type: CM

Failure Class: VSSL

Job Plan:

Planned Start:

Actual Start: 2/9/2011

Review Date:

PM/Bundle:

Planned Completion:

Actual Completion: 2/9/2011

Plant Information

RC: PERC01

Planner: WILLIAM STONEKING

MOC#:

When Code: RT

Lead Craft: MECH

MOC Status:

P&ID:

MOC Desc:

SIR/EIS Required:

LDAR

Tag #:

1st Attempt Made:

LDAR Planning Notes:

Leak Type:

1st Attempt Was:

LDAR Additional Notes:

Size:

1st Attempt Due By: 2/13/2011

Leak Location:

After 1st Attempt PPM:

Location Orientation:

Final Due By: 2/23/2011

Work Actuals Materials

Task ID	Stock No.	Noun Qualifier	PO	PO Line Num	Quantity
	400153	(R) Valve, Plug, 3" 150# Flanged, Xomox Tuflin,			1

Completed by Emp #: _____

Signature: _____